

MP, Tg, and Structure of Common Polymers

Melting Point (MP) and Glass Transition Temperature (Tg) are the most important thermodynamic parameters for the common polymers. These properties can be easily and quickly determined by DSC.

- Melting point temperature range (°C)
- Glass transition temperature range (°C)

